

Case Study #8: Roof Analysis

Client: Timberidge Custom Home, Heber City, Utah

Issue: It happens, sometimes people make mistakes in dimensioning or go off of old plans or things change, but in this example, the trusses over the Study in this house do NOT sit on the wall. Granted, field-measurement, if done, may have prevented this, but so does modeling it in advance and pointing this out to the truss company to correct in advance.

